

B120i 3
..... 3
..... 3

b120i_
Last update: 2019/09/28 17:24 - https://atl.kr/dokuwiki/doku.php/b120i_%EB%93%9C%EB%9D%BC%EC%9D%B4%EB%B2%84_%EA%B4%80%EB%A0%A8_%EC%84%A4%EC%B9%98_%EB%B0%A9%EB%B2%95

B120i

: <https://x1fingers.asuscomm.com/wordpress/gen8-esxi-disk-performance-issue/>

```
#  
$ esxcli system maintenanceMode set -e true  
  
#  
$ esxcli network firewall ruleset set -e true -r httpClient  
  
# tmp  
$ cd /tmp  
  
#  
$ wget  
http://downloads.hpe.com/pub/softlib2/software1/pubsw-linux/p1749737361/v98767/hpvsas-5.5.0-88.zip  
  
#  
$ unzip hpvsas-5.5.0-88.zip  
  
#  
$ cp scsi-hpvsas-5.5.0-880EM.550.0.0.1331820.x86_64.vib /var/log/vmware/  
  
#  
$ esxcli software vib remove -n scsi-hpvsas -f  
  
#  
$ esxcli software vib install -v file:scsi-hpvsas-5.5.0-880EM.550.0.0.1331820.x86_64.vib --force --no-sig-check --maintenance-mode  
  
# ESXi  
$ esxcli network firewall ruleset set -e false -r httpClient  
$ esxcli system maintenanceMode set --enable false  
$ esxcli system module set --enabled=false --module=vmw_ahci  
$ reboot
```

- hpvsas-5.5.0-88.zip
- scsi-hpvsas-5.5.0.102-1oem.550.0.0.1331820.x86_64.zip
- scsi-hpvsas-5.5.0.108-1oem.550.0.0.1331820.x86_64.zip

• <https://support.hpe.com/hpesc/public/km/product/5293150/Product#t=DriversandSoftware&sort>

Last update: 2019/09/28 17:24 b120i_ https://at1.kr/dokuwiki/doku.php/b120i_%EB%93%9C%EB%9D%BC%EC%9D%B4%EB%B2%84_%EA%B4%80%EB%A0%A8_%EC%84%A4%EC%B9%98_%EB%B0%A9%EB%B2%95

[=%40kmswtypesort_ko%20ascending&f:@kmssoftwaretypekey=\[swt8000113\]&f:@kmswtarg
etproductbaseenvironmentlatest=\[5293150_VMware\]](#)

From: <https://at1.kr/dokuwiki/> - AllThatLinux!

Permanent link: https://at1.kr/dokuwiki/doku.php/b120i_%EB%93%9C%EB%9D%BC%EC%9D%B4%EB%B2%84_%EA%B4%80%EB%A0%A8_%EC%84%A4%EC%B9%98_%EB%B0%A9%EB%B2%95

Last update: 2019/09/28 17:24

