

IPMI	PXE	3
		3

IPMI

PXE

OS CDROM USB OS
 가 . CDROM USB OS가
 BIOS 가 IPMI 가

- once pxe boot (pxe boot . boot order)

```
$ ipmitool -I lanplus -H hostip -p 6231 -U root -P password chassis bootdev pxe
```

- persistent pxe boot (boot order boot .)

```
$ ipmitool -I lanplus -H hostip -p 6231 -U root -P password chassis bootparam set bootflag force_pxe
```

- [IPMI](#)
- <https://www.jacobbaek.com/563> [Jacob Baek's home]
- http://coffeenix.net/board_print.php?bd_code=1765

From: <https://at1.kr/dokuwiki/> - AllThatLinux!

Permanent link: https://at1.kr/dokuwiki/doku.php/ipmi%EB%A5%BC_%ED%86%B5%ED%95%9C_pxe%EB%B6%80%ED%8C%85_%EC%88%9C%EC%84%9C_%EC%84%A4%EC%A0%95

Last update: 2021/07/27 06:33

