

<b>IPMI</b>	<b>PXE</b>	.....	3
		.....	3



# IPMI

# PXE

OS CDROM USB OS  
 가 . OS가  
 BIOS 가 IPMI 가

- once pxe boot ( pxe boot . boot order )

```
$ ipmitool -I lanplus -H hostip -p 6231 -U root -P password chassis bootdev pxe
```

- persistent pxe boot ( boot order boot .)

```
$ ipmitool -I lanplus -H hostip -p 6231 -U root -P password chassis bootparam set bootflag force_pxe
```

- [IPMI](#)
- <https://www.jacobbaek.com/563> [Jacob Baek's home]
- [http://coffeenix.net/board\\_print.php?bd\\_code=1765](http://coffeenix.net/board_print.php?bd_code=1765)

From: <https://at1.kr/dokuwiki/> - AllThatLinux!

Permanent link: [https://at1.kr/dokuwiki/doku.php/ipmi%EB%A5%BC\\_%ED%86%B5%ED%95%9C\\_pxe%EB%B6%80%ED%8C%85\\_%EC%88%9C%EC%84%9C\\_%EC%84%A4%EC%A0%95](https://at1.kr/dokuwiki/doku.php/ipmi%EB%A5%BC_%ED%86%B5%ED%95%9C_pxe%EB%B6%80%ED%8C%85_%EC%88%9C%EC%84%9C_%EC%84%A4%EC%A0%95)

Last update: 2021/07/27 06:33

